LAW OFFICES

BRODSKY & SMITH, LLC

9595 WILSHIRE BLVD., SUITE 900 BEVERLY HILLS, CA 90212

> 877.534.2590 FAX 310.247.0160 www.brodsky-smith.com

NEW JERSEY OFFICE 1040 KINGS HIGHWAY NORTH, STE 650 CHERRY HILL, NJ 08034. 856.795.7250 NEW YORK OFFICE 240 MINEOLA BOULEVARD MINEOLA, NY 11501 516.741.4977 PENNSYLVANIA OFFICE TWO BAŁA PLAZA, STE 510 BALA CYNWYD, PA 19004 610.667.6200

July 27, 2016

Shunwa Shin	Gold Mountain Recycling, Inc.
Owner	c/o Shunwa Shin
Gold Mountain Recycling, Inc.	Agent for Service of Process
1910 E Olympic Blvd	1910 E Olympic Blvd
Los Angeles, CA 90021	Los Angeles, CA 90021
Eddie Eum	Samuel Unger, Executive Officer
Manager	Regional Water Quality Control Board
Gold Mountain Recycling, Inc.	Los Angeles Region
1910 E Olympic Blvd	320 West Fourth Street, Suite 200
Los Angeles, CA 90021	Los Angeles, CA 90013
Gina McCarthy, Administrator	Thomas Howard, Executive Director
U.S. Environmental Protection Agency	State Water Resources Control Board
Mail Code: 1101A	1001 I Street
1200 Pennsylvania Avenue, N.W.	Sacramento, CA 95814
Washington, DC 20460	
Jared Blumenfeld, Regional Administrator	
U.S. EPA, Region 9	
75 Hawthorne Street	
San Francisco, CA 94105	

Re: Notice of Violation and Intent to File Suit under the Clean Water Act

To Whom It May Concern:

Brodsky & Smith LLC ("Brodsky Smith") represents Javier Flores ("Flores") a citizen of the State of California. This letter is to give notice that Brodsky Smith, on Flores' behalf, intends to file a civil action against Gold Mountain Recycling, Inc. ("Gold Mountain") for violations of the Federal Water Pollution Control Act, 33 U.S.C. § 1251 et seq. ("Clean Water Act" or "CWA") at Gold Mountain's facility located at 1910 E Olympic Blvd, Los Angeles, CA 90021 (the "Facility").

Flores is a citizen of the State of California who is concerned with the environmental health of the Los Angeles River, and uses and enjoys the waters of the Los Angeles River, its inflows, and other areas of the overall Los Angeles River Watershed. Flores' use and enjoyment of these waters are negatively affected by the pollution caused by Gold Mountain's operations. Additionally, Flores acts in the interest of the general public to prevent pollution in these waterways, for the benefit of their ecosystems, and for the benefits of all individuals and communities who use these waterways for various recreational, educational, and spiritual purposes.

This letter addresses Gold Mountain's unlawful discharge of pollutants from the Facility via stormwater City of Los Angeles storm drain system which directs Gold Mountain's discharges directly into

the Los Angeles River. Specifically, investigation of the Facility has uncovered significant, ongoing, and continuous violations of the CWA and the National Pollutant Discharge Elimination System ("NPDES") General Permit No CAS000001 [State Water Resources Control Board] Water Quality Orders No. 2014-0057-DWQ (the "Industrial Stormwater Permit") and 92-12-DWQ (as amended by Order No. 97-03-DWQ) (the "Previous Industrial Stormwater Permit").

CWA section 505(b) requires that sixty (60) days prior to the initiation of a civil action under CWA section 505(a), a citizen must give notice of his or her intent to file suit. 33 U.S.C. § 1365(b). Notice must be given to the alleged violator, the U.S. Environmental Protection Agency ("EPA"), and the State in which the violations occur. As required by section 505(b), this Notice of Violation and Intent to File Suit provides notice to Gold Mountain of the violations that have occurred and which continue to occur at the Facility. After the expiration of sixty (60) days from the date of this Notice of Violation and the Intent to File Suit, Flores intends to file suit in federal court against Gold Mountain under CWA section 505(a) for the violations described more fully below.

During the 60-day notice period, Flores is willing to discuss effective remedies for the violations noticed in this letter. We suggest that Gold Mountain contact Flores' attorneys at Brodsky & Smith within the next twenty (20) days so that these discussions may be completed by the conclusion of the 60-day notice period. Please note that we do not intend to delay the filing of a complaint in federal court, and service of the complaint shortly thereafter, even if discussions are continuing when the notice period ends.

I. THE LOCATION OF THE ALLEGED VIOLATIONS

A. The Facility

Gold Mountain's Facility is located at 1910 E Olympic Blvd. Los Angeles, California. At the Facility, Gold Mountain operates as a metal waste management recycling and scrap center. At the Facility, the following industrial activities occur: (i) collecting raw scrap metals from industrial scrap metal producers, dealers, and individual scrap metal collectors; (ii) the weighing and separating of base materials; (iii) drop off of scrap materials; (iv) torch cutting of scrap metal; (v) baling of scrap metal; storage of scrap metal; (vi) shipping of scrap metal. Other activities carried out in the regular course of business at the facility include storage of fuel and other oils, maintenance, equipment storage, and waste storage. Repair and maintenance activities carried out at the facility include, but are not limited to, electrical, plumbing. roofing, asphalt, concrete, and utilities repairs as well as janitorial duties. Possible pollutants from the Facility include total suspended solids ("TSS"), waste oils, lubricants, fuel, trash, debris, hazardous materials, chemical oxygen demand ("COD"), oil and grease, pH, heavy metals, such as aluminum, iron, copper, zinc, lead, and other pollutants. Stormwater from the Facility discharges, indirectly, into the Los Angeles River via the City of Los Angeles storm drain system.

B. The Affected Water

The Los Angeles River and overall Los Angeles River Watershed are waters of the United States. The CWA requires that water bodies such as the Los Angeles River, and overall Los Angeles River Watershed meet water quality objectives that protect specific "beneficial uses." The beneficial uses of the Los Angeles River and overall Los Angeles River Watershed include commercial and sport fishing, estuarine habitat, fish migration, navigation, preservation of rare and endangered species, water contact and non-contact recreation, shellfish harvesting, fish spawning, and wildlife habitat. Contaminated stormwater from the Facility adversely affects the water quality of the Los Angeles River and overall Los Angeles River Watershed, and threatens the beneficial uses and ecosystem of these watersheds, which includes habitats for threatened and endangered species.

¹ On April 1, 2014, the State Water Resources Control Board adopted an updated NPDES General Permit for Discharges Associated with Industrial Activity, Water Quality Order No. 2014-57-DWQ, which has taken force or effect on its effective date of July 1, 2015. As of the effective date, Water Quality Order No. 2014-57-DWQ has superseded and rescinded the prior Industrial Stormwater Permit except for purposes of enforcement actions brought pursuant to the prior permit.

II. THE FACILITY'S VIOLATIONS OF THE CLEAN WATER ACT

It is unlawful to discharge pollutants to waters of the United States, such as the Los Angeles River, without an NPDES permit or in violation of the terms and conditions of an NPDES permit. CWA § 301(a), 33 U.S.C. § 1311(a); see also CWA § 402(p), 33 U.S.C. § 1342(p) (requiring NPDES permit issuance for the discharge of stormwater associated with industrial activities). The Industrial Stormwater Permit authorizes certain discharges of stormwater, conditioned on compliance with its terms.

Gold Mountain has submitted a Notice of Intent ("NOI") to be authorized to discharge stormwater from the Facility under the Industrial Stormwater Permit since at least 2013. However, information available to Flores indicates that stormwater discharges from the Facility have violated several terms of the Industrial Stormwater Permit and the CWA. Apart from discharges that comply with the Industrial Stormwater Permit, the Facility lacks NPDES permit authorization for any other discharges of pollutants into waters of the United States.

A. Discharges in Excess of BAT/BCT Levels

The Effluent Limitations of the Industrial Stormwater Permit prohibit the discharge of pollutants from the facility in concentrations above the level commensurate with the application of best available technology economically achievable ("BAT") for toxic pollutants² and best conventional pollutant control technology ("BCT") for conventional pollutants.³ Industrial Stormwater Permit § I(D)(32), II(D)(2); Previous Industrial Stormwater Permit, Order Part B(3). The EPA has published Benchmark values set at the maximum pollutant concentration present if an industrial facility is employing BAT and BCT, as listed in Attachment 1 to this letter.⁴

Additionally, the Previous Industrial Stormwater Permit notes that effluent limitation guidelines for several named industrial categories have been established and codified by the Federal Government. See Previous Industrial Stormwater Permit pp. VIII. The Previous Industrial Stormwater Permit mandates that for facilities that fall within such industrial categories, compliance with the listed BAT and BCT for the specified pollutants listed therein must be met in order to be in compliance with the Previous Industrial Stormwater Permit. Id. Gold Mountain falls within these named industrial categories and it must have complied with the effluent limitations found therein in order to have been in compliance with the Previous Industrial Stormwater Permit during its effective period. In addition, the Industrial Stormwater Permit requires dischargers to comply with Effluent Limitations "consistent with U.S. EPA's 2008 Multi Sector General Permit for Stormwater Discharges Associated with Industrial Activity (the "2008 MSGP")". See Industrial Stormwater Permit § I(D)(33). The 2008 MSGP has specific numeric effluent limitations based upon Stand Industrial Classification ("SIC") codes. Notably, Gold Mountain, is classified as falling under SIC code 5093, relating to Scrap and Waste Recycling Facilities, requiring it to be within numerical effluent limitations for (i) Chemical Oxygen Demand (COD); (ii) Total Suspended Solids (TSS); (iii) Aluminum Total Recoverable; (iv) Total Copper; (v) Total Recoverable Iron; (vi) Total Lead; and (vii) Total Zinc Based on Gold Mountain's self-reporting data and/or lack thereof, Gold Mountain has not met this requirement and was in violation of the Previous Stormwater Permit over a period of approximately (3) years.

² BAT is defined at 40 C.F.R. § 437.1 *et seq*. Toxic pollutants are listed at 40 C.F.R. § 401.15 and include copper, lead, and zinc, among others.

³ BCT is defined at 40 C.F.R. § 437.1 *et seq*. Conventional pollutants are listed at 40 C.F.R. § 401.16 and include BOD, TSS, oil and grease, pH, and fecal coliform.

⁴ The Benchmark values are part of the EPA's Multi-Sector General Permit ("MSGP") and can be found at: http://www.epa.gov/npdes/pubs/msgp2008_finalpermit.pdf. See 73 Fed. Reg. 56, 572 (Sept. 29, 2008) (Final National Pollutant Discharge Elimination System (NPDES) General Permit for Stormwater Discharges From Industrial Activities).

Gold Mountain's self-reporting of industrial stormwater discharges show a pattern of exceedances of Benchmark values in every instance of self-reporting. *See* Attachment 2. This pattern of exceedances of benchmark values and lack of self-reporting indicate that Gold Mountain has failed and is failing to employ measures that constitute BAT and BCT in violation of the requirements of the Industrial Stormwater Permit and Previous Industrial Stormwater Permit. Flores alleges and notifies Gold Mountain that its stormwater discharges from the Facility have consistently contained and continue to contain levels of pollutants that exceed Benchmark Values for TSS.

Gold Mountain's ongoing discharges of stormwater containing levels of pollutants above EPA Benchmark values and BAT and BCT based levels of control also demonstrate that Gold Mountain has not developed and implemented sufficient Best Management Practices ("BMPs") at the Facility. Proper BMPs could include, but are not limited to, moving certain pollution-generating activities under cover or indoors capturing and effectively filtering or otherwise treating all stormwater prior to discharge, frequent sweeping to reduce build-up of pollutants on-site, installing filters on downspouts and storm drains, and other similar measures.

Gold Mountain's failure to develop and/or implement adequate pollution controls to meet BAT and BCT and the Facility violates and will continue to violate the CWA and the Industrial Stormwater Permit each and every day Gold Mountain's discharges stormwater without meeting BAT/BCT. Flores alleges that Gold Mountain has discharged stormwater containing excessive levels of pollutants from the Facility to the Los Angeles River during at least every significant local rain event over 0.2 inches in the last three (3) years.⁵ Attachment 3 compiles all dates in the last three (3) years when a significant rain event occurred. Gold Mountain is subject to civil penalties for each violation of the Industrial Stormwater Permit and the CWA within the past three (3) years.

B. Discharges Impairing Receiving Waters

The Industrial Stormwater Permit's Discharge Prohibitions disallow stormwater discharges that cause or threaten to cause pollution, contamination, or nuisance. *See* Industrial Stormwater Permit § III; Previous Industrial Stormwater Permit, Order Part A(2). The Industrial Stormwater Permit also prohibits stormwater discharges to surface or groundwater that adversely impact human health or the environment. *See* Industrial Stormwater Permit § VI(b)-(c); Previous Industrial Stormwater Permit, Order Part C(1). Receiving Water Limitations of the Industrial Stormwater Permit prohibit stormwater discharges that cause or contribute to an exceedance of applicable Water Quality Standards ("WQS") contained in a Statewide Water Quality Control Plan or the applicable Regional Water Board's Basin Plan. *See* Industrial Stormwater Permit § VI(a); Previous Industrial Stormwater Permit at Order Part C(2). Applicable WQS are set forth in the California Toxic Rule ("CTR")⁶ and Chapter 3 of the Los Angeles Region (Region 4) Water Quality Control Plan (the "Basin Plan"). *See* Attachment 1. Exceedances of WQS are violations of the Industrial Stormwater Permit, the CTR, and the Basin Plan.

The Basin Plan establishes WQS for all Inland Surface and Coastal waters of Los Angeles and Ventura Counties, including but not limited to the following:

 Waters shall not contain suspended or settleable material in concentrations that cause nuisance or adversely affect beneficial users.

⁵ Significant local rain events are reflected in the rain gauge data available at: http://www.ncdc.noaa.gov/cdo-web/search.

⁶ The CTR is set forth at 40 C.F.R. § 131.38 and is explained in the Federal Register preamble accompanying the CTR promulgation set forth at 65 Fed. Reg. 31, 682 (May 18, 2000).

⁷ The Basin Plan is published by the Los Angeles Regional Water Quality Control Board at: http://www.waterboards.ca.gov/losangeles/water_issues/programs/basin_plan/basin_plan_documentation.shtml.

- Waters shall be free of changes in turbidity that cause nuisance or adversely affect beneficial uses. Increases in natural turbidity attributable to controllable water quality factors shall not exceed 20% where natural turbidity is between 0 and 50 nephelometric turbidity units ("NTU"), and shall not exceed 10% where the natural turbidity is greater than 50 NTU.
- All waters shall be maintained free of toxic substances in concentrations that are toxic to, or that produce detrimental physiological responses in, human, plant, animal, or aquatic life.
- Surface waters shall not contain concentrations of chemical constituents in amounts that adversely affect any designated beneficial use.

Flores alleges that Gold Mountain's stormwater discharges have caused or contributed to exceedances of Receiving Water Limitations in the Industrial Stormwater Permit and the WQS set forth in the Basin Plan and CTR. These allegations are based on Gold Mountain's self-reported data submitted to the Los Angeles Regional Water Quality Control Board. These sampling results indicate that Gold Mountain's discharges are causing or threatening to cause pollution, contamination, and/or nuisance; adversely impacting human health or the environment; and violating applicable WQS. For example, Gold Mountain's sampling results indicate exceedances of WQS for copper, lead, zinc, iron, aluminum, COD, and TSS. See Attachment 2.

Flores alleges that each day that Gold Mountain has discharged stormwater from the Facility, Gold Mountain's stormwater has contained levels of pollutants that exceeded one or more of the Receiving Water Limitations and/or applicable WQS in the Los Angeles River. Flores alleges that Gold Mountain has discharged stormwater exceeding Receiving Water Limitations and/or WQS from the Facility to the Los Angeles River during at least every significant local rain event over 0.2 inches in the last three (3) years. See Attachment 3. Each discharge from the Facility that violates a Receiving Water Limitation or has caused or contributed, or caused or contributes, to an exceedance of an applicable WQS constitutes a separate violation of the Industrial Stormwater Permit and the CWA Gold Mountain is subject to penalties for each violation of the Industrial Stormwater Permit and the CWA within the past three (3) years.

C. Failure to Develop and Implement an Adequate Stormwater Pollution Prevention Plan

The Industrial Stormwater Permit requires dischargers to develop and implement an adequate Storm Water Pollution Prevention Plan ("SWPPP"). See Industrial Stormwater Permit, § X(B); Previous Industrial Stormwater Permit § A(1)(a). The Industrial Stormwater Permit also requires dischargers to make all necessary revisions to existing SWPPPs promptly. See Industrial Stormwater Permit, § X(B); Previous Industrial Stormwater Permit at Order Part E(2).

The SWPPP must include, among other requirements, the following: a site map, a list of significant materials handled and stored at the site, a description and assessment of all Gold Mountain pollutant sources, a description of the BMPs that will reduce or prevent pollutants in stormwater discharges, specification of BMPs designed to reduce pollutant discharge to BAT and BCT levels, a comprehensive site compliance evaluation completed each reporting year, and revisions to the SWPPP within 90 days after a facility manager determines that the SWPPP is in violation of any requirements of the Industrial Stormwater Permit. See Industrial Stormwater Permit, § X(A); Previous Industrial Stormwater Permit Section § A.

Based on information available to Flores, Gold Mountain has failed to prepare and/or implement an adequate SWPPP and/or failed to revise the SWPPP to satisfy each of the requirements of § X(A) of the Industrial Stormwater Permit and/or § A Previous Industrial Stormwater Permit. For Example, Gold Mountain SWPPP does not include and/or Gold Mountain has not implemented adequate BMPs designed to reduce pollutant levels in discharges to BAT and BCT levels in accordance with Section A(8) of the Industrial Stormwater Permit, as evidenced by the data in Attachment 2.

Accordingly, Gold Mountain has violated the CWA each and every day that it has failed to develop and/or implement an adequate SWPPP meeting all of the requirements of § X(A) of the Industrial Stormwater Permit and/or § A Previous Industrial Stormwater Permit, and Gold Mountain will continue to be in violation every day until it develops and implements an adequate SWPPP. Gold Mountain is subject to penalties for each violation of the Industrial Stormwater Permit and the CWA occurring within the past three (3) years.

D. Failure to Develop and Implement an Adequate Monitoring and Reporting Program and to Perform Annual Comprehensive Site Compliance Evaluations

The Industrial Stormwater Permit requires facility operators to develop and implement a Monitoring and Reporting Program ("MRP"). See Industrial Stormwater Permit, § XI; Previous Industrial Stormwater Permit § B(1) and Order Part E(3). The Industrial Stormwater Permit requires that MRP ensure that each the facility's stormwater discharges comply with the Discharge Prohibitions, Effluent Limitations, and Receiving Water Limitations specified in the Industrial Stormwater Permit. Id. Facility operators must ensure that their MRP practices reduce or prevent pollutants in stormwater and authorized non-stormwater discharges as well as evaluate and revise their practices to meet changing conditions at the facility. Id. This may include revising the SWPPP as required by § X(A) of the Industrial Stormwater Permit and/or § A Previous Industrial Stormwater Permit.

The MRP must measure the effectiveness of BMPs used to prevent or reduce pollutants in stormwater and authorized non-stormwater discharges, and facility operators must revise the MRP whenever appropriate. *See* Industrial Stormwater Permit, § XI; Previous Industrial Stormwater Permit § at Section B. The Industrial Stormwater Permit requires facility operators to visually observe and collect samples of stormwater discharges from all drainage areas. *Id.* Facility operators are also required to provide an explanation of monitoring methods describing how the facility's monitoring program will satisfy these objectives. *Id.*

Gold Mountain has been operating the Facility with an inadequately developed and/or inadequately implemented MRP, in violation of the substantive and procedural requirements set forth in Section B of the Industrial Stormwater permit. For example, the data in Attachment 2 indicates that Gold Mountain's monitoring program has not ensured that stormwater dischargers are in compliance with the Discharge Prohibitions, Effluent Limitations, and Receiving Water Limitations of the Industrial Stormwater Permit as required by the Industrial Stormwater Permit, § XI and/or the Previous Industrial Stormwater Permit § B. The monitoring has not resulted in practices at the Facility that adequately reduce or prevent pollutants in stormwater as required by Industrial Stormwater Permit, § XI and/or the Previous Industrial Stormwater Permit § B. Similarly, the data in Attachment 2 indicates that Gold Mountain's monitoring program has not effectively identified or responded to compliance problems at the Facility or resulted in effective revision of the BMPs in use or the Facility's SWPPP to address such ongoing problems as required by Industrial Stormwater Permit, § XI and/or the Previous Industrial Stormwater Permit § B.

As a part of the MRP, the Industrial Stormwater Permit specifies that Facility operators shall collect stormwater samples during "the first hour of discharge from (1) the first storm event of the wet season, and (2) at least one other storm event in the wet season." *See* Industrial Stormwater Permit, § XI(C) and/or the Previous Industrial Stormwater Permit § B(5)(a). Furthermore, should facility operators fail to collect samples from the first storm event of the wet season, they are still required to collect samples from two other storm events during the wet season, and explain in the annual report why the first storm event was not sampled. *Id.* Despite this requirement Gold Mountain has submitted the annual report for the 2015-2016 reporting period with no testing data whatsoever. Furthermore, Gold Mountain has submitted only one lab report with testing data for that time period. Additionally, Gold Mountain has failed to adequately explain why such sampling was not included.

As a result of Gold Mountain's failure to adequately develop and/or implement an adequate MRP at the Facility, Gold Mountain has been in daily and continuous violation of the Industrial Stormwater Permit and the CWA each and every day for the past three (3) years. These violations are ongoing. Gold Mountain will continue to be in violation of the monitoring and reporting requirement each day that Gold

Mountain fails to adequately develop and/or implement an effective MRP at the Facility. Gold Mountain is subject to penalties for each violation of the Industrial Stormwater Permit and the CWA occurring for the last three (3) years.

E. Unpermitted Discharges

Section 301(a) of the CWA prohibits the discharge of any pollutant into waters of the United States unless the discharge is authorized by a NPDES Permit issued pursuant to Section 402 of the CWA. See 33 U.S.C. §§ 1311(a), 1342. Gold Mountain sought coverage for the Facility under the Industrial Stormwater Permit, which states that any discharge from an industrial facility not in compliance with the Industrial Stormwater Permit "must be either eliminated or permitted by a separate NPDES permit." Industrial Stormwater Permit, § III; Previous Industrial Stormwater Permit, Order Part A(1). Because Gold Mountain has not obtained coverage under a separate NPDES permit and has failed to eliminate discharges not permitted by the Industrial Stormwater Permit, each and every discharge from the Facility described herein not in compliance with the Industrial Stormwater Permit has constituted and will continue to constitute a discharge without CWA Permit coverage in violation of section 301(a) of the CWA, 33 U.S.C. § 1311(a)

IV. PERSON RESPONSIBLE FOR THE VIOLATIONS

Gold Mountain Recycling, Inc. is the person responsible of the violations at the Facility described above.

V. NAME AND ADDRESS OF NOTICING PARTY

Javier Flores 1564 E. 112th St., Apt. 1042 Los Angeles, CA 90059 (310) 722-8496

VI. COUNSEL

Evan J. Smith, Esquire
esmith@brodsky-smith.com
Ryan P. Cardona, Esquire
rcardona@brodsky-smith.com
Brodsky & Smith, LLC
9595 Wilshire Blvd., Suite 900
Beverly Hills, CA 90212
T: (877) 534-2590
F: (310) 247-0160

VII. REMEDIES

Flores intends, at the close of the 60-day notice period or thereafter, to file a citizen suit under CWA section 505(a) against Gold Mountain for the above-referenced violations. Flores will seek declaratory and injunctive relief to prevent further CWA violations pursuant to CWA sections 505(a) and (d), 33 U.S.C. § 1365(a) and (d), and such other relief as permitted by law. In addition, Flores will seek civil penalties pursuant to CWA section 309(d), 33 U.S.C. § 1319(d), and 40 C.F.R. § 19.4, against Gold Mountain in this action. The CWA imposes civil penalty liability of up to \$37,500 per day per violation for violations occurring after January 12, 2009. 33 U.S.C. § 1319(d); 40 C.F.R. § 19.4. Flores will seek to recover attorneys' fees, experts' fees, and costs in accordance with CWA section 505(d), 33 U.S.C. § 1365(d).

As noted above, Flores and his Counsel are willing to meet with you during the 60-day notice period to discuss effective remedies for the violations noted in this letter. Please contact me to initiate these discussions.

Sincerely,

Evan J. Smith, Esquire esmith@brodsky-smith.com

Ryan P. Cardona, Esq. rcardona(a)brodsky-smith.com

Brodsky & Smith, LLC

9595 Wilshire Boulevard, Suite 900

Beverly Hills, CA T: (877) 534-2590

F: (310) 247-0160

ATTACHMENT 1: EPA BENCHMARKS AND WATER QUALITY STANDARDS FOR DISCHARGES TO FRESHWATER

A. EPA Benchmarks, 2008 Multi-Sector General Permit ("MSGP")

Parameter	Units	Benchmark Value	Source
Chemical Oxygen Demand	Mg/L	120	2008 MSGP
(COD)			
Total Suspended Solids	Mg/L	100	2008 MSGP
(TSS)			
Aluminum Total	Mg/L	0.75	2008 MSGP
Recoverable			
Total Copper	Mg/L	0.0038-0.0332*	2008 MSGP
Total Recoverable Iron	Mg/L	1.0	2008 MSGP
Total Lead	Mg/L	0.014-0.262*	2008 MSGP
Total Zinc	Mg/L	0.04-0.26*	2008 MSGP

^{*}Dependent on Freshwater Hardness Range

B. Water Quality Standards – Discharge Limitations and Monitoring Requirements (40 CFR Part 131.38 (California Toxics Rule or CTR), May 18, 2000)

Parameter	Units	Water Quality Objectives		Source
		4- Day Average	1-Hr Average	
Lead	Mg/L	0.0081	0.21	40 CFR Part 131.38
Zinc	Mg/L	0.081	0.090	40 CFR Part 131.38

ATTACHMENT 2: TABLE OF EXCEEDENCES FOR GOLD MOUNTAIN RECYCLING, INC.

The following table contains each stormwater sampling result which exceeds EPA Benchmarks and/or causes or contributes to an exceedance of CFR and/or Basin Plan Water Quality Standards. All EPA Benchmarks and CFR and/or Basin Plan Water Quality Standards are listed in Attachment 1. All stormwater samples were reported by the Facility during the past five (5) years.

Reporting Period	Sample Date	Parameter	Result	Unit
2015-2016	04/08/2016	TSS	768	Mg/L
2014-2015	05/14/2015	Aluminum, Total	3.55	Mg/L
2014-2015	05/14/2015	Copper, Total	0.671	Mg/L
2014-2015	05/14/2015	Iron, Total	2.92	Mg/L
2014-2015	05/14/2015	Zinc, Total	4.77	Mg/L
2013-2014	02/28/2014	TSS	524	Mg/L
2013-2014	02/28/2014	Copper, Total	0.371	Mg/L
2013-2014	02/28/2014	Zinc, Total	1.38	Mg/L
2013-2014	02/28/2014	Iron, Total	2.56	Mg/L
2013-2014	12/19/2013	Copper, Total	4.1	Mg/L
2013-2014	12/19/2013	Lead, Total	2.63	Mg/L
2013-2014	12/19/2013	Zinc, Total	6.53	Mg/L
2013-2014	12/19/2013	Iron, Total	24.1	Mg/L
2013-2014	12/19/2013	Aluminum, Total	25.6	Mg/L
2013-2014	12/19/2013	COD	1770	Mg/L
2013-2014	12/19/2013	TSS	779	Mg/L
2013-2014	12/19/2013	Copper, Total	0.503	Mg/L
2013-2014	12/19/2013	Zinc, Total	1.4	Mg/L
2013-2014	12/19/2013	Iron, Total	3.38	Mg/L
2013-2014	12/19/2013	Aluminum, Total	2.4	Mg/L
2013-2014	12/19/2013	Copper, Total	2.09	Mg/L
2013-2014	12/19/2013	Lead, Total	1.51	Mg/L
2013-2014	12/19/2013	Zinc, Total	4.63	Mg/L
2013-2014	12/19/2013	Iron, Total	17.9	Mg/L
2013-2014	12/19/2013	Aluminum, Total	17.3	Mg/L
2013-2014	12/19/2013	COD	897	Mg/L
2013-2014	12/19/2013	TSS	524	Mg/L

^{*}No Testing Results for any effluent limit contained in the submitted 2015-2016 annual report.

^{*}Submitted Lab Testing forms contain only one stormwater sampling date for the 2015-2016 period. Said Lab Testing does not contain testing results for Zinc or Copper

ATTACHMENT 3: ALLEGED DATES OF EXCEEDANCES BY GOLD MOUNTAIN RECYCLING, INC. January 1, 2013 – July 18, 2016

Days with precipitation two-tenths of an inch or greater, as reported by NOAA's National Climatic Data Center, Station: Los Angeles Downtown USC, CA US, GHCND:USW00093134, when a stormwater discharge from the Facility is likely to have occurred. http://www.ncdc.noaa.gov/cdo-web/search

2014	2015	2016
2/27	1/10	1/5
2/28	1/11	1/6
3/1	2/22	1/7
4/1	3/1	1/31
10/31	3/2	2/17
11/30	5/14	2/18
12/2	7/18	3/6
12/3	9/15	3/7
	10/5	3/11
	12/19	
	2/27 2/28 3/1 4/1 10/31 11/30	2/27 1/10 2/28 1/11 3/1 2/22 4/1 3/1 10/31 3/2 11/30 5/14 12/2 7/18 12/3 9/15 12/12 10/5